## **Amendments to the Written Description**

Please amend the written description as follows:

[0023] It is clear that this aspect has a negative influence on the performance of the prostatic prosthetic implant because the stem results to be partially detached from the femur, not to speak of the clear troubles that this situation causes for the patient's health.

[0055] One can also see in heavy lines, the osteotomy line [[N]]  $\underline{\mathbf{M}}$  along which the head  $\mathbf{T}$  of the femur  $\mathbf{F}$  is being cut to allow to work the femoral canal  $\mathbf{N}$ .

[0070] More particularly the profile [[A']] <u>8'</u> is preferably but not necessarily constituted by a first stretch **8b** connected to the mixtilinear surface **7** with a generally constant cross section and a second stretch **8c** extending until under the bridge **7c** with a widened crossed section.